

Appendix C: NetApp UL Certificate



Northbrook, IL San Jose, CA Melville, NY
A not-for-profit organization dedicated to public safety
and committed to quality service

File No: BP6295 CCN: CRZH
Service Center No: 725
Expires: 01/09/2013
Issued: 01/09/2008

NATIONAL INDUSTRIAL SECURITY BURGLAR ALARM SYSTEM CERTIFICATE

THIS CERTIFIES that the *Alarm Service Company* is included by Underwriters Laboratories Inc. (UL) in its Directory as qualified to use the *UL Listing Mark* in connection with the certificated *Alarm System*. This Certificate is the *Alarm Service Company's* representation that the *Alarm System* including all connecting wiring and equipment has been installed and will be maintained in compliance with requirements established by UL. This Certificate does not apply in any way to the installation of any additional signaling systems, such as; fire, smoke, waterflow, burglary, holdup, medical emergency, or otherwise, that may be connected to or installed along with the Certificated *Alarm System*. This Certificate does not apply in any way to the communication channel between the protected property and any facility that monitors signals from the protected property unless the use of a UL listed or Classified Alarm Transport Company is specified on the Certificate.

LIMITATION OF LIABILITY: Underwriters Laboratories Inc. makes no representations or warranties, express or implied, that the *Alarm System* will prevent any loss by fire, smoke, water damage, burglary, hold-up or otherwise, or that the *Alarm System* will in all cases provide the protection for which it is installed or intended. UL may at times conduct inspections of the *Alarm Service Company* including inspections of representative installations made by it. UL does not assume or undertake to discharge any liability of the *Alarm Service Company* or any other party. UL is not an insurer and assumes no liability which may result directly or indirectly from inspection of the equipment, failure of the equipment, failure to conduct inspections, incorrect certification, nonconformity with requirements, failure to discover nonconformity with requirements, cancellation of the Certificate or withdrawal of the *Alarm Service Company* from inclusion in UL's

Alarm System Description:

Protected Area: BUILDING #3, ROOM #3.3.223
System Type: Alarmed Room Extent of Protection: 3
Line Security: Encrypted
Alarm Sounding Device: Inside
Monitored Signals: Alarms, Troubles, Openings, and Closings
Alarm Investigator Response Time: 5 min.
Alarm Transmission Method: Data Network and Data Network
Cognizant Security Field Office: BOLLING AFB, DC

Remote Monitoring Site: (UL Listed Central Station)
File No: BP2072 Service Center Number: 111
HSM ELECTRONIC PROTECTION SERVICES INC
SUITE 300
6000 NATHAN LN N
MINNEAPOLIS MN 55442

Alarm Investigator: (Private Guard Company)
SECURITAS
475 E JAVA DR
SUNNYVALE, CA 94089

Protected Property:



Alarm Service Company:

HSM ELECTRONIC PROTECTION SERVICES INC
SUITE 113
48377 FREMONT BLVD
FREMONT CA 94538

[Signature]
Alarm Service Company's Representative

Date 3-7-2008

SN: DS89316405